



Improving Stripping Procedures



- 1 Install a solution tank on machine, to add additional weight and have stripper available for dry spots.



- 2 Install an oversize floor pad driving assembly, with a riser. Riser must be 2" larger than machine apron. Use for stripping all edges and eliminate doodle bugging. Clean corners with a razor blade.



- 3 Purchase from Home Depot Plumbing Dept. a 3/4" Flange and a 3/4" Nipple 6 inches long. Attach to top of machine motor with screws.



- 4 Purchase from Wal-Mart, 2 - 25 lb. weights.



- 5 Place 1 - 25 lb. weight on any 1 HP low speed machine.



- 6 Place 2 - 25 lb. weights on any 1 1/2 HP low speed machine.

Note: By adding additional weight to your low speed machine, you will increase the stripping ability of your machine.